

How to Update the Midmark PDF Converter driver


Problem

This knowledge article details the process for updating the Driver of the Midmark PDF Converter from Amyuni Document Converter 400 to Amyuni Document Converter 450

Solution

Step 1


- Open the .cab file by double clicking it
- Highlight all the contents of the .cab file (see screenshot below) and copy them




- Paste them to a specific folder of your choice which you have full access and rights

Step 2


- Launch Control Panel
- Select Devices and Printers from the item list
- Locate the Midmark PDF Converter in the Printers region
- Right click on the Midmark PDF Converter and select Printer Properties




- Select the Advanced tab




- In the driver region click the New Driver button
- The Add Printer Driver Wizard will open then just click on the Next button
- The next window will ask if you have the driver under the Windows Update or if you Have Disk
- Select/click the Have Disk button
- Browse to where you extracted the contents of the downloaded .cab file
- Select the Amyuni Document Converter 450 from the list



- Select/click the Next button
- Select/click the Finish button
- You should now see the selected driver as Amyuni Document Converter 450



Step 3



- Select/Click the Security tab
- Under Group or user names, make sure all listed groups/user names have full permissions (Allow)
- Once all group/user names have full permissions, select/click the OK button

