

# Midmark Anesthetic Record Interface (ARI)

## Technical Requirements



The following technical requirements are necessary to ensure successful communication between the Midmark Multiparameter Monitor and Midmark Anesthetic Record Interface software.

Midmark partners with Animal Care Technologies (ACT) to onboard and support customers. ACT uses proprietary software called PracticeSync™ to collect the data from the Midmark Multiparameter Monitor and write it back into the third-party practice management software.

### Midmark Multiparameter Monitor

To enable PracticeSync™ to communicate with the Midmark Multiparameter Monitor, the monitor must be connected to the same Wi-Fi network as the server/computer on which PracticeSync™ software is installed.

### Computers

These requirements are for any computer on which PracticeSync™ is installed. This includes both the server (or computer used as the install location for the central software) and any others on which the user interface is installed.

- Minimum operating system requirements are Windows® 7 SP1 or above for PC versions or Windows® Server 2012 R2 or above for server versions.
- The person within your hospital who is designated as your installation contact must have administrative rights on all computers on which PracticeSync™ will be installed (including your practice management server or whichever computer is used as the install location for the central software).
- To enable PracticeSync™ to communicate with the Midmark Multiparameter Monitor, the monitor must be connected to the same Wi-Fi network as the server/computer on which PracticeSync™ software is installed.

PracticeSync™ is a trademark of Animal Care Technologies.  
Windows® is a registered trademark of Microsoft Corporation